

# Fact Sheet – Slab Duct



Size Testing



Seam Strength testing



## Common Issues

- Seams that break apart during tensioning.
- Joins that burst apart during tensioning.
- Low quality steel with rippled surfaces.
- Lack of quality control and steel coil feed transparency.
- In-consistent tension results due to impedance within the duct.
- Lack of rack storage system that limits easy transport and causes high levels of damage and spoilage.
- Unsafe crane lifting practices on-site.
- Profiles that do not offer efficient grout consumption.
- Inconsistent product availability when you need it.



## Millform Advantage

- Our ISO 9001 certification guarantees quality.
- Manufactured here in Australia for 40 years and tested to the highest tolerance levels to assure we exceed durability and rigidity standards.
- Batch tracking and Mill certificates for every product.
- Special technology and techniques used to produce a product that will not impede strand and tension results.
- Interconnecting housing that ensure secure joins that will not leak or break apart.
- In-house transport company and racking system that is certified.
- Made in Australia ensures availability and fast delivery where and when you need it.

### Millform Products

22 Shale Place, Eastern Creek NSW 2766 – Ph 02 9832 6900  
10 Racecourse Road, Albury NSW 2640 – Ph 02 6025 4377

[www.millform.com.au](http://www.millform.com.au)

